WALL/ROOF POLISHER
Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS
REPLACEMENT SHEET






FIG 1




FIG 1B




FIG 1C




FIG 2




FIG 3A




FIG 3B






FIG 3C


Ganxing Ke


Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS

REPLACEMENT SHEET













FIG 5B








FIG 6










FIG 7A




FIG 7B

# WALL/ROOF POLISHER Ganxing Ke Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS REPLACEMENT SHEET




FIG 8




FIG 9A

Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS
REPLACEMENT SHEET




FIG 9B





FIG 10




**FIG 11** 

Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS
REPLACEMENT SHEET

Top journey 2 (higher than top journey 1) Descend Relay Normally closed O2 Ο2 Bottom journey C1 常开 Emergency stop Switch .40V Ascend Top Relay journey 1 01 C2 Normally open Transformer 01 Contactor CI N 220V O2 Contactor C2

Fig 12



**FIG 12B** 




FIG 13

Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS
REPLACEMENT SHEET




FIG 14




FIG 15